# 3DXORBIT command

1946  GstarCAD MY /KW  July 30, 2021  [CAD Commands](#)   0  1149

The **3DXORBIT** command is used to orbit along the Z axis.

**Command Access:**

**Ribbon** : View >Navigate 2D>Orbit along the Z-axis

Online URL: https://www.gstarcad.com.my/knowledge/article/3dxorbit-command-1946.html