

Super Axonometric

1060 GstarCAD Malaysia June 30, 2021 [Unique function](#) 0 3719


It is a quintessential function that can easily convert a plan drawing to an axonometric drawing.

Menu : Express > GstarCAD Tools > Super Axonometric

Command Entry : ZC


Operation steps:

- 1.Start the command.
- 2.Select objects and press enter, as shown below.



- 3.Enter the axonometric point of view, such as 45 degree.

- 4.The effect will be as below.



Online URL: <https://www.gstarcad.com.my/knowledge/article/super-axonometric-1060.html>