

How to create 2D isometric drawing?

1092 GstarCAD Malaysia June 30, 2021 [Tips & Tricks](#) 0 6014

If you work in plant industry, then you might need to draw isometric drawings.

If you use GstarCAD, you can do it easily by using snap command and changing its style to isometric. Also you can change drawing plane by typing ISOPLANE command.

If you use GstarCAD, you may wish you can do it easily. It's not a 3D drawing, but 2D drawing by simply change your drawing orientation. You can do it by using snap, then change its style to isometric.

2D ISOMETRIC

Command: SNAP

Specify snap spacing or [ON/OFF/Aspect/Style/Type] : S

Enter snap grid style [Standard/Isometric] : I

~~Specify vertical spacing : 10.~~

