


# Plot Transparency

1258 GstarCAD Malaysia June 30, 2021 [Workflow](#) 0 4615

Plot Transparency option in plot dialog box, specifies whether object transparency is plotted.

This option should only be used when plotting drawings with transparent objects. For performance reasons, plotting transparency is disabled by default. This option can be overridden by the PLOTTRANSPARENCYOVERRIDE system variable.



Online URL: <https://www.gstarcad.com.my/knowledge/article/plot-transparency-1258.html>