

LAYERPMODE command

2177 GstarCAD MY /KW August 17, 2021 [CAD Commands](#) 0 917

The **LAYERPMODE** command is used to turn on or turn off trace mode about layer settings.

Command Access:

Command : LAYERPMODE

LAYERPMODE command

Enter LAYERP mode [ON/OFF] <ON>:

Function Description:

If the LAYERP mode is turned on, layer changes will be traced. If the LAYERP mode is turned off, layer changes will not be traced.

Online URL: <https://www.gstarcad.com.my/knowledge/article/layerpmode-command-2177.html>