

Batch Print

2724 GstarCAD MY /KW December 7, 2021 [Workflow](#) 0 1570

Batch print drawings with the same drawing frame attribute.

Menu : Express tools>Plot Tool>Batch Print

Command Entry : BP

Operation steps:

1. Start the command.
2. Specify the type of frame, you can select Layer/ Block/ Polyline so that the system can recognize the frame.
3. Corner select the frame you want to print, you will get a dialog box as below.

Batch Plot Setup [X]

Specify batch setup

Filter Base: layer 0 [v] [Select from drawing]

Current window: (21.94,259.12),(267.23,62.53) [Re-specify selected box]

According to the selected info, need to plot 2 frames [Draw frame boxes]

Plot Setup_Options

Plotter Name: Canon MF4400 Series UFR II LT [v]

Page Name: Model Paper Size: A4 [v]

With Plot styles: Yes Style Table: None [v]

Plot Linewidths: Yes Drawing Orientation: Portrait&Not upside-down

Orientation

Center Offset X= 0.000000 Y= 0.000000

Plot

Plot Objects: Plot to file [v]

Prefix Name: PLOT_ Extended Name: .PLT Delete existed duplicate file

Saved Location: E:\Program Files\GstarCAD2013 Profess [Browse...]

Plot Scale

Fit Paper Fixed Scale Scale 1.000000 : 1.000000

Units: Millimeter

[OK] [Apply to Layout] [Cancel]

4. Set the print Parameters, click "OK" to execute bath print.

Online URL: <https://www.gstarcad.com.my/knowledge/article/batch-print-2724.html>