

## **3DXORBIT command**

1946 GstarCAD MY /KW July 30, 2021 [CAD Commands](#) 0 1138

The **3DXORBIT** command is used to orbit along the Z axis.

### **Command Access:**

**Ribbon** : View >Navigate 2D>Orbit along the Z-axis

Online URL: <https://www.gstarcad.com.my/knowledge/article/3dxorbit-command-1946.html>