ACISOUT command

1951 GstarCAD MY /KW July 30, 2021 CAD Commands 0 777

The ACISOUT command is used to export a body object, solid, or region to an ACIS file.

Command Access:

Command: ACISOUT

Command Prompts:

Select object: select the object and press ENTER

Function Description:

If the selected object is not a solid or region object, it will be ignored and displays the "Create ACIS File" dialog box; inputting the file name to be created, the selected object will be exported to an ASCII file.

Online URL: https://www.gstarcad.com.my/knowledge/article/acisout-command-1951.html