


CDORDER command

2025 GstarCAD MY /KW August 6, 2021 [CAD Commands](#) 0 1046

The **CDORDER** command Set the drawing order of selected objects by their color number.

Command Access:

Command : CDORDER



You can specify the drawing order by the color priority, the first color on the left list is in front and the last color is in back.

Online URL: <https://www.gstarcad.com.my/knowledge/article/cdorder-command-2025.html>