

DIMCENTER command

2078 GstarCAD MY /KW April 15, 2022 [CAD Commands](#) 0 1595

The **DIMCENTER** command is used to create center marks or center lines for circles or arcs.

Command Access:

Ribbon : Annotation > Dimension > DIMCENTER

Menu : Dimension > Center Mark


Command : DIMCENTER

Command Prompts:


Select arc or circle:

Function Description:

The circle center could display as center mark or center lines. Users could set options of Center marks in Dimension Style Manager in Symbols and Arrows tab.



Users could change display of center mark or modify its size in Dimension Style Manager. They could also change its settings by DIMCEN system variable.



Related tutorial video:

- [Dimstyle command](#) 00:27
- [Dimlinear command](#) 02:29
- [Menus and Shortcut Menus](#) 02:41
- [Dimaligned command](#) 02:51
- [Dimangular command](#) 03:11
- [Dimarc command](#) 03:19
- [Dimradius command](#) 03:31
- [Dimdiameter](#) 03:41
- [Dimcontinue command](#) 04:08
- [Dimbaseline command](#) 04:46
- [Dimcenter](#) 05:07
- [QDIM command](#) 05:30
- [Menus and Shortcut Menus](#) 07:05
- [Properties command](#) 07:08
- [Propertiesclose command](#) 07:08
- [Dimbreak command](#) 07:43
- [Menus and Shortcut Menus](#) 08:34
- [Dimreassociate command](#) 08:52
- [Dimtoffset command](#) 09:19
- [Dimregen command](#) 09:29

Above video sources from [TUTORIAL - GETTING STARTED WITH GSTARCAD](#), enrol now for free.

Online URL: <https://www.gstarcad.com.my/knowledge/article/dimcenter-command-2078.html>