

# HIDEOBJECTS command

2150 GstarCAD MY /KW August 16, 2021 [CAD Commands](#) 0 1143

The **HIDEOBJECTS** command is used to hide selected objects.

## Command Access:

**Menu** : Tools > Isolation > Hide Objects

**Command** : HIDEOBJECTS

**Shortcut** : right-click in the drawing area and select Isolation, click "Hide Objects"

## Command Prompts:

Select object:

## Function Description:

Users could hide selected objects. All other objects are visible.

Online URL: <https://www.gstarcad.com.my/knowledge/article/hideobjects-command-2150.html>