VPMIN command

2431 GstarCAD MY /KW August 25, 2021 <u>CAD Commands</u> 0 995 The **VPMIN** command is used to restore the current viewport.

Command Access:

Command: VPMIN

Function Description:

The settings of circle center and scale factor will be restored as maximized before.

Online URL: https://www.gstarcad.com.my/knowledge/article/vpmin-command-2431.html