


## Create Ordinate Dimensions

2571 GstarCAD MY /KW November 9, 2021 [Workflow](#) 0 914

An ordinate dimension annotates the perpendicular distance from an origin or base point (the origin of the current [UCS](#)).

Ordinate dimensions consist of an x- or y-coordinate and a leader. The ordinate dimension text is always aligned with the ordinate leader lines, independent of the text orientation of the current dimension style.



Online URL: <https://www.gstarcad.com.my/knowledge/article/create-ordinate-dimensions-2571.html>